ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0196, W0099, W0194, W0111, W0190, W0192, W0188, W

Street Name
NA, Om Shakthi Lyt 3rd Crs

Significant Landmark
Kirloskar layout

Segment No.
14/C-W0196/S051119

Total Length (m)
1167.49

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	193.09	77.500306	13.069108	77.500073	13.067377	4th main	3rd main
2	118.63	77.500306	13.068816	77.501277	13.069310	3rd main	20th cross
3	135.51	77.500563	13.068542	77.500389	13.067329	3rd main	4th main
4	48.70	77.501028	13.068444	77.501459	13.068323	th main	3rd main
5	128.10	77.501584	13.068792	77.500563	13.068210	1st main	26th cross
6	86.22	77.502289	13.067806	77.501517	13.067992	1st main	navy layout
7	91.89	77.501351	13.067741	77.500530	13.067943	3rd main	27th cross
8	117.65	77.502514	13.067482	77.501459	13.067733	3rd main	1st cross
9	93.56	77.501310	13.067434	77.500463	13.067595	1st main	3rd main
10	154.14	77.502746	13.067118	77.501360	13.067426	1st main	3rd main

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads and drains cross roads at Klrloskar layout in ward 14

Sanctioned Estimated Amount (Rs.)
40

Sanctioned Year
2014-2015-

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details

Job No. / Work Code
014-15-000026

Work Order No.
EE/DD/WO/260-2014-2015

Work Order Date
28/02/2015

Period of Extention

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #
No

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೊಮ್ಮನಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ

DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0196, W0099, W0194, W0111, W0190, W0192, W0188, W

Date: 13/04/2016 Time: 17:40:25 RH 20160413174025 Page 1 of 1